

Equipamentos SLA Algar		Responsável	Vinicius Gonçalves	Data	13/03/2018
-------------------------------	--	-------------	--------------------	------	------------

Item	Equipamento	Modelo	Marca	SN	Placas			Preventiva						Observações	
					ASI SCR	GBE	Módulo QAM	1	2	3	4	5	6		
1	Multiplexador	ProStream 1000 ACE	Harmonic	041049056	3	2	-	OK	OK	OK	OK	OK	OK	OK	Mux 1
2	Multiplexador	ProStream 1000 ACE	Harmonic	041116057	3	2	-	OK	OK	OK	OK	OK	OK	OK	spare
3	Multiplexador	ProStream 1000 ACE	Harmonic	041146035	3	2	-	OK	OK	OK	OK	OK	OK	OK	Mux 3
4	Multiplexador	ProStream 1000 ACE	Harmonic	041146037	3	2	-	OK	OK	OK	OK	OK	OK	OK	Mux 2
5	Multiplexador	ProStream 1000 ACE	Harmonic	052401964	3	2	-	OK	OK	OK	OK	OK	OK	OK	Mux 4
6	Multiplexador	ProStream 1000 ACE	Harmonic	052401965	3	2	-	OK	OK	OK	OK	OK	OK	OK	Mux 5
7	Multiplexador	ProStream 1000 ACE	Harmonic	053394084	3	2	-	OK	OK	OK	OK	OK	OK	OK	spare
8	Modulado QAM	NSG9000 6G	Harmonic	241044165 / 461232251	-	-	3	OK	OK	OK	OK	OK	OK	OK	Araguari
9	Modulado QAM	NSG9000 6G	Harmonic	241102040 / 461050575	-	-	3	OK	OK	-	OK	OK	OK	OK	spare
10	Modulado QAM	NSG9000 6G	Harmonic	241105199 / 461050577	-	-	3	OK	OK	OK	OK	OK	OK	OK	Image (A. Fern.)
11	Modulado QAM	NSG9000 6G	Harmonic	241146062 / 461137713	-	-	Ø	OK	OK	-	OK	OK	OK	OK	spare
12	Modulado QAM	NSG9000 6G	Harmonic	241147087 / 461137893	-	-	3	OK	OK	OK	OK	OK	OK	OK	HE
13	Multiplexador	TS9600-8	Tecsys	AKDALE00001	-	-	-	OK	OK	OK	OK	OK	OK	OK	spare
14	Multiplexador	TS9600-8	Tecsys	AKDALE00002	-	-	-	OK	OK	OK	OK	OK	OK	OK	OK
15	Multiplexador	TS9600-8	Tecsys	ALGALE00004	-	-	-	OK	OK	OK	OK	OK	OK	OK	OK
16	Multiplexador	TS9600-8	Tecsys	AMCALE00004	-	-	-	OK	OK	OK	OK	OK	OK	OK	OK
17	Multiplexador	TS9600-8	Tecsys	AMDALE00005	-	-	-	OK	OK	OK	OK	OK	OK	OK	spare

- 01 - Conferência de SN e Placas
- 02 - Versões de firmware Mux - 06.08.10.001
- 03 - No active alarms
- 04 - Versões de firmware NSG - 02.07.03.006
- 05 - Versões de firmware Tecsys - 2.0